Copyright © 1999 WSDOT TDO Interchange Viewer: SR 529 - Marine View Dr/Walnut St NOT TO SCALE Not for use for engineering or other purposes requiring dimensional accuracy For any accidents coded to the P1 ramp with a Y, the SRMP in TRIPS must be changed from 0.18 to 0.00. Snohomish River (0.00)-(0.01)529 P1 00482B (Pocific Hwy) L<sub>(0.16)</sub> (Pacific Hwy) (0.12) MP 3.80 (0.00) 529 R5 00380 (0.14)¬ MP 4.91B-(0.07) SR 5 Exit 198 (0.06) Broadway St SB (Old SR 529) MP 3.74 Broadway St NB (Old SR 529) MP 4.92B Begin physical gap MP 0.00 LX (0.10) (0.07)529 LX 00492B 529 Q5 00374 (0.00)NOTE:

## NOTE: Because of physical gap, SR 529 mileposting stops at MP 4.92B and resumes at MP 3.74 at SPS of oxing. SR 529 Junction Marine View Dr/Walnut St Everett, Snohomish County WSDOT Northwest Region NOT TO SCALE 8/3/2001 KLK

Walnut St